



PERSONNEL QUALIFICATIONS

Marita R. Ellis | Associate III



EDUCATION

- University of Oklahoma
 - Bachelor of Science, Architectural Engineering, 2018
 - Master of Science, Civil Engineering, Structural Focus, 2019

PRACTICE AREAS

- Repair and Rehabilitation
- Historic Preservation
- Condition Assessment
- Facade Assessment
- Water/Air Leakage Assessment
- Historic Structures Reports

PROFESSIONAL AFFILIATIONS

- American Society of Civil Engineers
- Architectural Engineering Institute
- Association for Preservation Technology

CONTACT

mellis@wje.com
703.641.4601
www.wje.com

EXPERIENCE

Since joining WJE in 2019, Marita Ellis has been involved in a variety of projects, including repair and rehabilitation design, facade condition assessments and investigations, waterproofing consulting, and construction observation services for new, existing, and historically significant structures. Ms. Ellis's services have included a variety of facade systems, including masonry cavity and mass walls, historic wood windows, aluminum-framed windows, and curtain walls. Her building material experience includes stone, brick, and terra cotta masonry; below- and above-ground waterproofing; wood; and concrete.

REPRESENTATIVE PROJECTS

Repair and Rehabilitation

- Russell Senate Office Building (1903–08, 1933, Architect of the Capitol), Capitol Hill - Washington, D.C.: Stone facade restoration construction period services, including seismic retrofit installation observation and reporting
- Senate Underground Garage and Plaza (1932, Architect of the Capitol), Capitol Hill - Washington, D.C.: Waterproofing replacement construction period services
- Hart Senate Office Building (1982, Architect of the Capitol), Capitol Hill - Washington, D.C.: Development of facade repair contract documents
- Regal Rockville Center - Rockville, MD: Water leakage investigation and development of hot-applied rubberized waterproofing replacement design and construction documents

Historic Preservation

- University of Virginia, Alderman Library (1937) - Charlottesville: Building envelope assessment of historic brick masonry, windows, engaged columns, wood cornice, and roof

Condition Assessment

- Virginia Department of Transportation Annex Building (1961) - Richmond: Investigation and evaluation of distress at limestone masonry facades, development of repair recommendations, and energy-efficient exterior wall section
- Pelican Walk Condominium - Panama City Beach, FL: Investigation of distress at fenestration to evaluate damage from Hurricane Michael

Facade Assessment

- University of Pittsburgh - PA: Facade ordinance inspections and condition assessment of five structures on the university campus and medical center

Water/Air Leakage Assessment

- Sheppard Pratt Health System - Elkridge, MD: Construction observation services, including water penetration and air leakage testing for compliance to construction documents

Historic Structures Reports

- Mount Gilead - Centreville, VA: Development of historic structures report for a 1785 Dutch Colonial to document history, condition, and treatment recommendations
- Sully Plantation Outbuildings - Chantilly, VA: Site work to develop building preservation plans for five historic outbuildings